Four Brothers Environmental, LLC.
9 Alden Avenue
Greenland, NH 03840

November 18, 2025

Asbestos Air Clearance Report

Street Address:
226 NH-120, Cornish
Cornish Flat, NH, USA

Attn:
Mr. Spiros Tzilianos
Trumbell-Nelson Construction Company
19 Plaza Heights Road
West Lebanon, NH 03784

Dear Mr. Tzilianos,

Please take this letter as notification that the above job site 226 NH-120, Cornish, Cornish Flat, NH, is in accordance with New Hampshire Env-A 1805.09. On November 18, 2025, an industrial hygienist conducted an asbestos visual inspection. No visible residue was identified by the industrial hygienist. After the abatement area passed the visual inspection, air clearance samples were collected by the project monitor and analyzed by a NIOSH-582 equivalent trained and proficient analyst via the NIOSH 7400 method, “A Rules”. Analytical results indicate that the fiber concentrations in the abatement work area(s) were below 0.010 fibers/cubic centimeters of air.

Please see the attached lab results. Please contact me if you have any questions.

Best regards,



Jacob Parker
Industrial Hygienist

Attachments:
Certificate of Visual Inspection
Analytical Results
Certifications

387-NH-25-001

Four Brothers Environmental, LLC.
9 Alden Avenue
Greenland, NH 03840

Certificate of Visual Inspection

FOUR BROTHERS
ENVIRONMENTAL

9 Alden Avenue
Greenland, NH 03840

Certificate of Visual Inspection

An asbestos visual inspection was conducted by a competent industrial hygienist in the below work area(s). The industrial hygienist did not identify any visible residue. The scope of work described herein is complete and the work area(s) passed visual inspection.

Date:	11/18/2025
Site Address:	226 NH-120, Cornish, Cornish Flat, NH
Client:	Spiros Tzilianos
Asbestos Contractor:	Envirovantage
Asbestos Supervisor:	Sergio Rodriguez AS001970R
Scope of Work:	Approximately 300 SF of tile and mastic removed via full containment.
Work Area(s):	Center of Community Center
Notes:	ACM was cut and removed whole.
Industrial Hygienist Name:	Jacob Parker
License Number:	N/A (NH)
Project Monitor Signature:	

Four Brothers Environmental, LLC.
9 Alden Avenue
Greenland, NH 03840

Analytical Results

Four Brothers Environmental, LLC.
9 Alden Avenue

ASBESTOS AIR MONITORING DATA

Site Address:	226 NH-120, Cornish. Cornish Flat, NH			**Project No:**	004-NH-25-002
Project Name:	Cornish Community Center Renovaiton			**Client:**	Alloy Group
Hygienist Name:	Jacob Parker	**Date:**	November 18, 2025	**Monitor License #:**	N/A - NH
Analyst Name:	Jacob Parker	**Date:**	November 18, 2025	**Lab License #:**	N/A - NH

Sample Number	Sample Location	Sample Type*	Work Activity**	Sampling Time (Minutes-Military format)			Flow Rate (Liters per Minute)			Total Volume (Liters)	Fiber Density (f/mm²)	Fiber Count #	**RESULT** Fibers/Cubic Centimeter
				Start	Stop	Total	Start	Stop	Average				
FB-01	**Field Blank**	OT	-	-	-	-	-	-	-	-	0	0.0	0
FB-02	**Field Blank**	OT	-	-	-	-	-	-	-	-	0	0.0	0
111825-4BE02-03	Community Center Containemnt Center	CL	6	10:46	12:02	76	15.90	15.90	15.90	1208.4	12.7	10.0	0.004

CHAIN-OF-CUSTODY

Relinquished by: Analyzed on Site
Printed Name:
Date:
Time:

Received By: Analyzed on Site
Printed Name:
Date:
Time:

Microscope ID # 4BE02
Rotameter ID # ROT02

Method: *NIOSH 7400, "A" Rules*

f/mm² - fibers per square millimeter
Effective Collection Area = 385 mm²
Microscopic Field Area = 0.00785 mm2
Fibers per 100 Fields unless specified

*Sample Type Codes

IWA = Inside Work Area
OWA = Outside Work Area
HEPA = HEPA Exhaust
BG = Background
PL = Personal
CL = Clearance
DF = Decontam. Facility
OT = Other

**Work Activity Codes

1 = Background
2 = Work Area Prep
3 = Asbestos Removal
4 = Waste Loadout
5 = Glovebag Removal
6 = Clearance Test
7 = Repair/Encapsulation
8 = Cleaning/Decontamination
9 = Pre-Abatement
10 = Gross Removal
11 = Fine Cleaning
12 = Soil Remediation
13 = Maintenance Activity
14 = Other

HSE/NPL Slide #: 55173

Phase rings aligned? **Yes** / No

Analyst Signature:

Four Brothers Environmental, LLC.
9 Alden Avenue
Greenland, NH 03840

Certifications



This is to certify that

Jacob B. Parker

7 North Browning Court, Pembroke, NH 03275
MA DLS Asbestos Project Monitor License# AM900839

has completed the requisite training by Video Conference, and has passed an examination for reaccreditation

Asbestos Project Monitor Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location
Zoom Video Conference
Institute for Environmental Education 16 Upton Drive Wilmington, MA 01887

June 18, 2025
Course Dates

25-5630-174-275237
Certificate Number

June 18, 2025
Examination Date

June 18, 2026
Expiration Date

Training Director

CERTIFICATE NUMBER

49695

Certificate of Attendance

ECOLOGICS™ TRAINING INSTITUTE

This is to Certify that

JACOB PARKER

Has Completed the Course of

AIR SAMPLING & ANALYSIS OF AIRBORNE ASBESTOS (NIOSH-582 EQUIVALENT)

UNDER TSCA 206, FOR PURPOSES OF COMPLIANCE WITH 29 CFR 1926.1101 AND TITLE 8 CCR 1529 AND TITLE 8 CCR 5208.

ARMANDO DUCOING
DIRECTOR

August 27, 2021	E082321NIOSH 082321	
COMPLETION DATE	CLASS NUMBER / STARTING DATE	CERTIFICATE EXPIRES

Ecologics Training Institute

2487 E Orangethorpe Ave . Fullerton, CA 92831 . Ph (714) 632-8100 . Fax (714) 632-8111 . www.ecologicsonline.com